

AUTOMOBILES
CITROËN
 CUSTOMER SERVICES
 AFTER-SALES TECHNICAL DEPARTMENT



N° 29 S

11st April 1973
 Confidential
 (All rights reserved)

COUNTRIES CONCERNED :

USA - CANADA

Since March 1973, these vehicles have been fitted with a buzzer warning device which warns the driver when the engine speed reaches 6400 r.p.m. (maximum engine speed not to be exceeded).

The buzzer is fixed to the console under the ash-tray and it is controlled by the fuel pump safety device, which is modified.

NOTE : The remarks on the OPERATION and REPARATION (test control) operations) of the fuel pump safety device, made in the Technical Bulletin N° 11 S of 13rd December 1971, remain the same.

REPLACEMENT PARTS.

ITEMS	NEW NUMBERS
Buzzer warning device AXO	1 S 5 441 151 W
Safety device JAEGER	1 S 5 436 711 K
Wiring harness	2 S 5 436 874 G

SM VEHICLES

(SB series SD)

ENGINE

Buzzer warning device

P.T.O.

